

Wiring Diagrams

Single Phase up to 3kw




Single Phase over 3kw



Three Phase star connection (4 wire)

Three Phase delta connection (3 wire)



ALL WORK SHOULD BE CARRIED OUT BY SUITABLY QUALIFIED PERSONNEL TO THE LATEST IEE REGULATIONS AND SITE REGULATIONS

All wiring and controls outside the box is the responsibility of the customer

12 Noddington Avenue, Whittington, Lichfield, Staffs, SS14 9NQ Office Tel/Fax: 01543 432661 Works Tel/Fax: 01827 703228

Email: sales@processheatingservices.com Web site: www.processheatingservices.com